

VEHICLE INSPECTION REPORT

FJ65VSC

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/10/2015

Year 2015

Mileage 493,425 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L446527

Body Style Fridge Box

Keys 2

Cab Type DAY CAB

Gearbox MANUAL

Rear Suspension Air

Rear Doors Barn

Tail Lift Tuckaway

****COLLECTED AS NON RUNNER STARTS AND DRIVES**** AD BLUE, THERMOKING T-800R FRIDGE UNIT, STANDBY PLUG

Tyres


| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows

Photos





Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Mirror Assy osf
Broken
Replace



5: Door osf
Dented
With Paint Damage



6: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

| | | | |
|--------------------------|-------|--|-------|
| Carpet Condition | - | Upholstery Condition | - |
| Seat Condition | - | Odour | - |
| Engine Runs | Fault | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | Fault | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | Fault | Oil warning light illuminated | Fault |
| Airbag light illuminated | OK | DPF light illuminated | Fault |
| ABS light illuminated | Fault | Service indicator light illuminated | Fault |

| | | | |
|---------|----|----------|----|
| Windows | OK | Radio | OK |
| | | Steering | OK |