

VEHICLE INSPECTION REPORT

MD68ZYH

SCANIA S500

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	03/01/2019	VIN	YS2S6X20005532352	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	940,500 Km Warranted	MOT Due	31/01/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	HIGHLINE CAB		
Colour	BLUE	Gearbox	AUTOMATIC		

CRACKED WINDSCREEN SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Air conditioning
- Leather seat trim

Photos





