

VEHICLE INSPECTION REPORT

SP63JLX

Ford Transit T350 2.2 TDCi 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 07/11/2013

Year 2013

Mileage 115,973 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTFXDP39594

Body Style Panel Van XLWB

MOT Due 08/11/2026

CAP Clean £1,925.00

CAP Average £1,475.00

CAP Below £1,000.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos






Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Roof
Rusted
Over 5mm



3: Bonnet
Rusted
Over 5mm

4: Wing nsf
Dented
Over 30mm



5: Door osf
Rusted
Over 5mm

6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Dented
With Paint Damage

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door nsr
Dented
With Paint Damage

10: B Post ns
Rusted
Over 5mm



11: Door nsf
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

-
-

Upholstery Condition
Odour

-
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK