

VEHICLE INSPECTION REPORT

PE17H XK

DAF LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	14/03/2017	VIN	XLRAEL1500L463433	Cab Type	DAY CAB
Year	2017	Body Style	Box Van	Gearbox	MANUAL
Mileage	993,149 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/03/2026	Tail Lift	Cantilever

COLLECTED AS NON-RUNNER, CAB CORROSION/GEARBOX/CLUTCH REQUIRES ATTENTION

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Sill of
Rusted
Over 5mm



3: Bonnet
Chipped
Multiple Chips

4: Wing osf
Cracked
Replace



5: Bumper Front
Dented
With Paint Damage

6: Door osf
Dented
With Paint Damage



7: Qtr Panel osr
Rusted
Over 5mm

8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsr
Rusted
Over 5mm

10: B Post ns
Dented
Over 30mm



11: Door nsf
Dented
With Paint Damage

12: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		

Windows

OK

Radio

OK

Steering

OK